	Туре	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	0	mode)and (high hear2 mode)and (low near2 mode)	ÚSPAT	2002/01/03 15:35
2	BRS	L2	0	vehicle and transmission and (all near2 wheel near2 mode)	USPAT	2002/01/03 15:36
3	BRS	L3	0	vehicle and transmission and (all same wheel same mode)	USPAT	2002/01/03 15:36
4	BRS	L4	0	vehicle and transmission and (all same mode)	USPAT	2002/01/03 15:36
5	BRS	L5	22617	vehicle and transmission and (mode)	USPAT	2002/01/03 15:37
6	BRS	L6	3340	<pre>vehicle and transmission and ((four near2 wheel near2 drive)or(low near2 mode)or (high near2 mode))</pre>	USPAT	2002/01/03 15:38
7	BRS	L7	154	<pre>vehicle and transmission and (four near2 wheel near2 drive)and((low near2 mode)or (high near2 mode))</pre>	USPAT	2002/01/03 15:42
8	BRS	L8	46	(torque near2 output) and (calibration near2 table)	USPAT	2002/01/03 15:45
9	BRS	L9	0	7 and 8	USPAT	2002/01/03 15:43
10	BRS	L10	129	(torque near2 output) and (calibration same table)	USPAT	2002/01/03 16:22
11	BRS	L11	0	7 and 10	USPAT	2002/01/03 15:43
12	BRS	L12	16228	torque near2 output	USPAT	2002/01/03 15:43
13	BRS	L14	1089	(calibration near2 table)	USPAT	2002/01/03 15:44
14	BRS	L15	0	7 and 14	USPAT	2002/01/03 15:44
15	BRS	L16	9591	calibrat\$4 same table	USPAT	2002/01/03 15:45
16	BRS	L17	2	7 and 16	USPAT	2002/01/03 15:45
17	BRS ·	L18	3417	four near2 wheel near2 drive	USPAT	2002/01/03 15:46
18	BRS	L19	0	8 and 18	USPAT	2002/01/03 15:46
19	BRS	L20	26265	(four near2 wheel near2 drive)or (low near2 mode)or (high near2 mode)	USPAT	2002/01/03 15:47
20	BRS	L21	59	14 and 20	USPAT	2002/01/03 15:47

	Туре	L #	Hits	Search Text	DBs	Time Stamp
21	BRS	L22	156	(four near2 wheel near2 drive)and((low near2 mode)or (high near2 mode))and transmission	USPAT	2002/01/03 15:48
22	BRS	L23	0	10 and 22	USPAT	2002/01/03 15:48
23	BRS	L13	65	7 and 12	USPAT	2002/01/03 16:07
24	BRS	L24	16	<pre>(torque near2 output) and (calibration same table) and ((low near2 mode) or (high near2 mode) or (all near2 wheel near2 drive))</pre>	USPAT	2002/01/03 15:51
25	BRS	L25	1247	((speed near2 parameter)or (engine near2 speed))and (manual near2 transmission)	USPAT	2002/01/03 16:08
26	BRS	L26	5	13 and 25	USPAT	2002/01/03 16:11
27	BRS	L27	633	(transmission near2 output near2 shaft near2 speed) and (automatic near2 transmission)	USPAT	2002/01/03 16:13
28	BRS	L28	3	13 and 27	USPAT	2002/01/03 16:14
29	BRS	L29	6330	calibration same table	USPAT	2002/01/03 16:14
30	BRS	L30	0	13 and 29	USPAT	2002/01/03 16:14
31	BRS	L31	72955	calibration	USPAT	2002/01/03 16:14
32	BRS	L32	0	13 and 31	USPAT	2002/01/03 16:14
33	BRS	<u>1</u> 33	2	(torque near2 output) and (calibration same table) and (four near2 wheel near2 drive)	USPAT	2002/01/03 16:24
34	BRS	L34	16	(torque near2 output) and (calibration same table) and ((low near2 mode) or (high near2 mode))	USPAT	2002/01/03 16:25